


WRIA 2, SAN JUAN ISLANDS

Riparian Condition



Distribution lines depict where riparian conditions were evaluated.
This data is derived from the Washington Shore Zone Inventory (Feb. 2001).
NOTE: Riparian conditions were only estimated for unconsolidated shorelines.
Table at left shows Riparian Percent, Riparian Length (at that percentage)
and Total length of unit within that percentage.

Map Projection: Lambert Conformal Conic (WA Stateplane South)
Zone: 5626 Datum: NAD 1927 Units: Feet
Data derived from DNR Hydrography, Resolution Scale 1:24000,
Transportation Resolution Scale 1:24000, Shorezone Inventory
Cartography By: Ronald McFarlane, NWIFC, December 2001



Northwest Indian
Fisheries Commission



Percent	Riparian Feet	Length
0	0	1518504
5	10415	206710
10	12118	117545
15	6106	40705
20	13971	63926
25	4680	18720
30	7997	25418
35	1221	3490
40	6190	15475
45	0	0
50	12227	24454
55	0	0
60	23371	38952
65	3352	5158
70	5840	8543
75	15037	20050
80	21678	27097
85	0	0
90	10302	11447
95	599	631
100	8451	8451
Evaluated		
Total	163556	636570
Total	163556	2155074